




Product Change Notification

Form No. QMCP-RF-18, A1

Title:	R1510 and R1511 hardware design improvement	Tracking No.	CPPCN 2025042501	Date of Issue	Apr. 25, 2025																																																
FOR DISTRIBUTION TO:		<input type="checkbox"/> for all customer <input checked="" type="checkbox"/> for specific customer <u>JP customer</u>			<input type="checkbox"/> With PPAP																																																
Product Identification	Effected Product:	R1510-4L R1511-4L-A04JP-A R1511-4L-A04JP-B																																																			
	Effected PN(B-code):	B048704 B061711 B061712																																																			
Types for Change	<input checked="" type="checkbox"/> Design / Firmware		<input type="checkbox"/> Material / Composition		<input type="checkbox"/> Quality / Reliability																																																
	<input checked="" type="checkbox"/> Data sheet		<input type="checkbox"/> Process / Manufacturing		<input type="checkbox"/> Test																																																
	<input type="checkbox"/> Packing/Shipping		<input type="checkbox"/> Manufacturing Location		<input checked="" type="checkbox"/> Other <u>PN</u>																																																
Description of Change	<p>1. Added power supply anti-reverse connection protection circuit. (Because some customers need to prevent wrong connection.) Update hardware will change to new order code and B-code, the product model will not changed, please check below:</p> <table><thead><tr><th colspan="3">Before</th><th colspan="3">After</th></tr><tr><th>Order code</th><th>B-code</th><th>Model</th><th>Order code</th><th>B-code</th><th>Model</th></tr></thead><tbody><tr><td>A004800715</td><td>B048704</td><td>R1510-4L</td><td>A004800723</td><td>B004800718</td><td>R1510-4L</td></tr><tr><td>A004800716</td><td>B048704</td><td>R1510-4L</td><td>A004800724</td><td>B004800718</td><td>R1510-4L</td></tr><tr><td>A006100732</td><td>B061711</td><td>R1511-4L-A04JP-A</td><td>A006100751</td><td>B006100743</td><td>R1511-4L-A04JP-A</td></tr><tr><td>A006100733</td><td>B061711</td><td>R1511-4L-A04JP-A</td><td>A006100752</td><td>B006100743</td><td>R1511-4L-A04JP-A</td></tr><tr><td>A006100734</td><td>B061712</td><td>R1511-4L-A04JP-B</td><td>A006100753</td><td>B006100744</td><td>R1511-4L-A04JP-B</td></tr><tr><td>A006100735</td><td>B061712</td><td>R1511-4L-A04JP-B</td><td>A006100754</td><td>B006100744</td><td>R1511-4L-A04JP-B</td></tr></tbody></table>					Before			After			Order code	B-code	Model	Order code	B-code	Model	A004800715	B048704	R1510-4L	A004800723	B004800718	R1510-4L	A004800716	B048704	R1510-4L	A004800724	B004800718	R1510-4L	A006100732	B061711	R1511-4L-A04JP-A	A006100751	B006100743	R1511-4L-A04JP-A	A006100733	B061711	R1511-4L-A04JP-A	A006100752	B006100743	R1511-4L-A04JP-A	A006100734	B061712	R1511-4L-A04JP-B	A006100753	B006100744	R1511-4L-A04JP-B	A006100735	B061712	R1511-4L-A04JP-B	A006100754	B006100744	R1511-4L-A04JP-B
	Before			After																																																	
	Order code	B-code	Model	Order code	B-code	Model																																															
	A004800715	B048704	R1510-4L	A004800723	B004800718	R1510-4L																																															
A004800716	B048704	R1510-4L	A004800724	B004800718	R1510-4L																																																
A006100732	B061711	R1511-4L-A04JP-A	A006100751	B006100743	R1511-4L-A04JP-A																																																
A006100733	B061711	R1511-4L-A04JP-A	A006100752	B006100743	R1511-4L-A04JP-A																																																
A006100734	B061712	R1511-4L-A04JP-B	A006100753	B006100744	R1511-4L-A04JP-B																																																
A006100735	B061712	R1511-4L-A04JP-B	A006100754	B006100744	R1511-4L-A04JP-B																																																
<p>2. Update TELEC, JATE certifications, the TELEC ID and JATE ID on the label will be changed. Please check below.</p> <p>3. Update the product label, including EAN 13 code. Please check below.</p> <p>R1510-4L:</p> <table><thead><tr><th></th><th>B-code</th><th>EAN-13</th><th>Label</th></tr></thead><tbody><tr><td>Before</td><td>B048704</td><td>6974316440222</td><td></td></tr></tbody></table>						B-code	EAN-13	Label	Before	B048704	6974316440222																																										
	B-code	EAN-13	Label																																																		
Before	B048704	6974316440222																																																			

	After	B004800718	6974316440383	<div> Industrial Cellular VPN Router Model: R1510-4L PN: B004800718 Power: 12/24VDC, 9~36VDC IP: 192.168.0.1 admin/admin MAC: aa:aa:aa:aa:aa:aa IMEI: 100000000000004 201-250273 018-190011 ADF18-0088018 P250062201 SN: 100000000000001 6 974316 440383 www.robustel.com Made in China </div>
	R1511-4L-A04JP-A:			
		B-code	EAN-13	Label
	Before	B061711	6974316440253	<div> Industrial Cellular VPN Router Model: R1511-4L-A04JP-A Series: R1511-4L PN: B061711 Power: 9-36 V --- IP: 192.168.0.1 admin/admin MAC: aa:aa:aa:aa:aa:aa IMEI: 100000000000004 211-211101 018-190011 ADF18-0088018 D220017211 SN: 100000000000001 6 974316 440253 www.robustel.com Made in China </div>
	After	B006100743	6974316440376	<div> Industrial Cellular VPN Router Model: R1511-4L-A04JP-A Series: R1511-4L PN: B006100743 Power: 12/24VDC, 9~36VDC IP: 192.168.0.1 admin/admin MAC: aa:aa:aa:aa:aa:aa IMEI: 100000000000004 201-250273 018-190011 ADF18-0088018 P250062201 SN: 100000000000001 6 974316 440376 www.robustel.com Made in China </div>
	R1511-4L-A04JP-B:			
		B-code	EAN-13	Label
	Before	B061712	6974316440260	<div> Industrial Cellular VPN Router Model: R1511-4L-A04JP-B Series: R1511-4L PN: B061712 Power: 9-36 V --- IP: 192.168.0.1 admin/admin MAC: aa:aa:aa:aa:aa:aa IMEI: 100000000000004 211-211101 018-190011 ADF18-0088018 D220017211 SN: 100000000000001 6 974316 440260 www.robustel.com Made in China </div>
	After	B006100744	6974316440369	<div> Industrial Cellular VPN Router Model: R1511-4L-A04JP-B Series: R1511-4L PN: B006100744 Power: 12/24VDC, 9~36VDC IP: 192.168.0.1 admin/admin MAC: aa:aa:aa:aa:aa:aa IMEI: 100000000000004 201-250273 018-190011 ADF18-0088018 P250062201 SN: 100000000000001 6 974316 440369 www.robustel.com Made in China </div>
Reason for Change	Hardware upgrades to improve product reliability.			
Anticipated Impact	Note: Anticipated (positive and negative) impact on form, fit, function, quality or reliability.			
	Form:	No effect.		
	Fit:	No effect.		

	Function:	<i>No effect.</i>
	Quality:	<i>No effect.</i>
	Reliability:	<i>Reliability will be improved.</i>
	Other Impact and Recommended Action:	<i>PN and product label.</i>
Qualification Plan Schedule	Date for Changed Product Samples:	April 2025
	Last Order Date for Unchanged Product:	Q2 2025
	Proposed Deploy Date for Changed Product:	Q2 2025
Contact Information	Guangzhou Robustel Co., Ltd. Address: 501, Building #2,63 Yongan Road, Huangpu District,Guangzhou, Guangdong Province, China Tel: +86-20-82321505 Email: pm@robustel.com	
Acknowledgement of PCN receipt	If no feedback is received within 30 days of the date of this notice, the product change notice will be deemed to have been accepted by default. Robustel will implement the changes as mentioned above.	